

- VCC 103.1.1
- VEBC Table of Contents
- 101.5 Use of Terminology and Notes
- Throughout – References to IFC construction requirements deleted
- Throughout – Deleted references to “dangerous” and “unsafe” provisions
- Throughout – Deleted “subject to the approval of the building official”
- 102.2 Scope
- 103.10 Construction Documents
- 202 Existing Building
- 202 Change of Occupancy
- 202 Repair
- 202 Work Area
- 302 Building Materials and Systems
- 303 Fire Escapes
- 304 Glass Replacement and Replacement Windows
- 306 Group B Teaching and Research Laboratories
- 307 Reroofing and Roof Repair
- Deletion – Smoke alarm retrofit requirements eliminated from 2012 VRC sections 402.5, 403.6, and 1104.1
- 402 Change of Occupancy
- 403 Additions
- 404 Alterations
- 404.3 Alterations Affecting an Area Containing a Primary Function
- 405 Historic Buildings
- Chapter 5 Repairs
- 501.1 Exception
- 602 Level 1 Alterations
- 603 Level 2 Alterations
- 604 Level 3 Alterations
- Alteration Provisions for Reroofing
- Chapter 7 Change of Occupancy
- 701.1 Exception
- 701.1 Scope
- 701.2 Work Undertaken in Connection with a Change of Occupancy
- 710.1 Exception
- Chapter 8 Additions
- Chapter 9 Historic Buildings
- Chapter 10 Moved Buildings
- Chapter 11 Retrofit Requirements
- Chapter 12 Construction Safeguards

Chapter 13

Chapter 14 Compliance Alternative for Change of Occupancy